



97250 HXTAL NYL-1

Information on Storage

HXTAL NYL-1 should be stored at room temperature 18 – 25°C.

Storage or transportation can lead to the formation of crystallized resin, which is shown by a milky appearance.

The transparency of the resin can be restored by warming it up to 50°C.

Bonding should be carried out with a clear resin.

The adhesive strength is not impaired by warming up the resin.

Technical recommendation of the producer – December 2014